



Synteko SUPER CLEAN 1697 is a wax-free combined cleaning and care agent with a high cleaning effect and an adapted care effect. The product is suitable for hardwood and cork floors treated with Synteko finishes. It leaves the cleaned surface with a thin, matte, lime-free, non-skid, antistatic film which is dissolved and renewed the next time the floor is washed. The film improves the wear resistance of the finish and keeps your floor looking beautiful. Due to its formula, which has a normal pH. Synteko SUPER CLEAN can be recommended for almost all finished surfaces. It is even suitable for clinker and stone floors. Synteko SUPER CLEAN does not leave a grey film on surface. It is easily soluble, even in cold water

How do I use SUPER CLEAN?

Vacuum or mop the floor to remove any dirt. Prepare Synteko SUPER CLEAN as follows:

- For normal cleaning, 1 part SUPER CLEAN to 50 parts
- For heavy cleaning, 2–3 parts SUPER CLEAN to 50 parts


First, pour the water into a bucket. Never pour water directly onto a wood floor. Dip a soft cloth or a sponge mop into the mixture and wring thoroughly before cleaning the floor. Synteko SUPER CLEAN is suitable for wet mops and combi-machines.



Synteko SUPER CLEAN Maintenance program for finished floors



NEWSHINE



Synteko NEWSHINE leaves a protective film which will help maintain the beautiful look of the floor for a longer period. Subsequent treatment or polishing are not necessary. Cleaning can be done with a damp mop without Synteko NEWSHINE being dissolved.

How do Luse NEWSHINE?

Before applying make sure that the floor is clean. Sweep. mop or vacuum the floor. Old soap, grease, polish etc. should be removed by washing with water and Synteko REMOVER. Apply Synteko NEWSHINE in a thin, even layer using a damp mop or a non-flocculent cloth. Leave the floor to dry for app. 30 minutes before walking on it.





Synteko REMOVER 1692 is a basic detergent which efficiently removes dirt, marks from rubber heels, shoe polish, lipstick, ink, soil and more. It is designed for use before sanding and recoating with Synteko floor finishes or new treatment with Synteko maintenance products such as NEWSHINE.

Note: Wax on a finished surface CANNOT be removed with Synteko REMOVER. Such floors must be sanded back to bare wood.

How do I use REMOVER?

Vacuum or mop the floor to remove any dirt. Prepare Synteko REMOVER as follows:

- For normal cleaning, ½ 1 part Synteko REMOVER to 100 parts water
- For heavy cleaning, 2–3 parts Synteko REMOVER to 100 parts water

Soak a cloth in the mixture; do not pour it directly onto the floor. Wet mop, let the mixture act for a few minutes and then dry mop. Further cleaning with 1 part vinegar to 9 parts water is recommended if sanding and recoating is to be done. The floor must be completely dry before screening and recoating.

Surfaces treated with Synteko finishes are easy to keep clean. Regular maintenance gives your floor long life.

AFTER FINISHING:

- the floor can be used (with caution) 8 hours after the last coat is applied
- furniture can be placed on the floor after 24 hours
- rugs can be placed on the floor after one week
- do not clean the floor with water or detergents for the first month
- attach felt pads to the legs of chairs and tables in order to avoid scratchina the finish

CHOOSE THE RIGHT PRODUCT FOR:

SUPER CLEAN regular cleaning NEWSHINE periodic cleaning special cleaning REMOVER

www.synteko.com

NB! Detailed information and instruction are provided on the Product Information sheet and MSDS (Material Safety Data Sheet) at www.svnteko.com. This folde only presents a selection of important

Company address



Synteko NEWSHINE Maintenance program for finished floors Synteko REMOVER Maintenance program for finished floors





Synteko SOAP 1617 is suitable for regular use after the treatment of wooden floors with Synteko floor oils. It can also be used for cleaning and maintenance of natural

How do I use SOAP?

Synteko SOAP

Maintenance program for oiled floors

When necessary, for regular cleaning, but no sooner than one week after oil treatment. Floors may be washed with a 1:20 dilution of Synteko SOAP in lukewarm water, using a well wrung cloth.



How do I use RE-COVER?

Clean the floor with a Synteko REMOVER solution. Make sure the floor is completely dry before applying Synteko RE-COVER. Apply it thinly with a rubber spatula, floor cloth or similar. Allow the floor to absorb the RE-COVER for 10–15 minutes before applying it again (if necessary). Let the surface dry for 20 minutes and polish the floor with a clean, dry, non-flocculent floor cloth. The floor may be used after 2-4 hours.







Synteko RE-COVER 1620 is an oil for periodic maintenance of floors treated with Synteko oils. How often you use it will depend on the amount of traffic and how often the floor is cleaned:

- normally every other year for residential areas
- appr. 2–4 times per year for commercial areas.

Be sure to begin regular maintenance before you wear through to the bare wood. Regular maintenance will restore your floor's lustre and keep it looking beautiful for very long time. You can also use RE-COVER for local



Synteko REMOVER

Synteko REMOVER 1692 is a basic detergent which efficiently removes dirt and soil. It is designed to be used before sanding and recoating with Synteko floor finishes or new treatment with Synteko maintenance products. Note: Wax on a oiled surface CANNOT be removed with Synteko REMOVER. Such floors must be sanded back to bare wood.

How do I use REMOVER?

Vacuum or mop the floor to remove any dirt. Prepare Synteko REMOVER as follows:

- Normal cleaning, ½ 1 part Synteko REMOVER to 100 parts water
- Heavy cleaning, 2–3 parts Synteko REMOVER to 100 parts water

Soak a cloth in the mixture; do not pour it directly onto the floor. Wet mop, let the mixture act for a few minutes and then dry mop. Further cleaning with 1 part vinegar to 9 parts water is recommended if sanding and recoating is to be done. The floor must be completely dry before screening and recoating.

Surfaces treated with Synteko oils are easy to keep clean. Regular maintenance gives your oiled floor long life.

AFTER OILING:

- the floor can be used 1-2 days after the last polishing
- do not wet a floor treated with Synteko floor oils during the first week
- vacuum or dry-mop floors regularly
- attach felt pads to the legs of chairs and tables in order to avoid scratching the surface

CHOOSE THE RIGHT PRODUCT FOR:

SUPER CLEAN regular cleaning NEWSHINE periodic cleaning REMOVER special cleaning

www.synteko.com

NB! Detailed information and instruction sheet and MSDS (Material Safety Data Sheet) at www.svnteko.com. This folder Maintenance program for oiled floors only presents a selection of important

Company address



